

### 1938-47 Pickup & Truck Body Parts


**Bitchin Products**  
**Street Rod Firewalls**  
**and Front Floorboards**  
*Steel*

**1937-39: Smallblock**  
 BN-371000 400.00 ea

**1940 Firewall: Smallblock**  
 BN-401000 325.00 ea

**1935-39 Floorboard**  
 BN-351002 325.00 ea

**1940 Floorboard**  
 BN-401002 250.00 ea




**1938-39 Floor and Transmission Cover (original type)**  
 81C-700378 Transmission cover 80.00 ea

**1940-47 Transmission Cover and seals (original type)**  
 01C-700378 Transmission cover, steel 75.00 ea  
 01C-700826 Transmission cover to floor seal 15.00 ea  
 01A-35190 Steering tube to floor seal, sponge rubber 5.00 ea  
 01C-8112145 Pedal & column seal cover plate set 30.00 ea


**1940-47 Pickup Floor Panels**  
 01C-835-TR Cab floor toe panel, RH 100.00 ea  
 01C-835-TL Cab floor toe panel, LH 100.00 ea  
 01C-835-C Floor center hump (behind trans cover) 50.00 ea  
 01C-835-FR Cab floor in front of seat, RH 1940-41 100.00 ea  
 01C-835-FL Cab floor in front of seat, LH 1940-41 100.00 ea  
 21C-835-FR Cab floor in front of seat, RH 1942-47 100.00 ea  
 21C-835-FL Cab floor in front of seat, LH 1942-47 100.00 ea  
 01C-855 Cab rear floor under seat, 1940-41 325.00 ea  
 (can be used 1942-47 if fuel tank not used)

**Patch Panels**



01C-114 Cowl patch panels, 1940-41 175.00 pr  
 01C-114-I Cowl inner panels, 1940-41 115.00 pr  
 01C-114-HP Hinge post patch, 1940-41 55.00 pr  
 01C-836 Door outer patch panels 65.00 pr  
 01C-836-I Door inner patch panels, formed 45.00 pr  
 01C-836-IS Door inner patch panels, die stamped 95.00 pr  
 01C-838 Cab sill panels 90.00 pr  
 01C-870-S Cab corner patch 90.00 pr  
 01C-850-BACK Cab back patch 60.00 ea

**COE Cab Over Patch Panels**



81Y-114 Cowl patch panels, 1940-41 150.00 pr  
 81Y-881-R Inner fender panel, RH 150.00 ea  
 81Y-881-L Inner fender panel, LH 150.00 ea  
 81Y-836 Door outer patch panels 60.00 pr  
 81Y-836-I Door inner patch panels, die stamped 120.00 pr  
 81Y-870 Cab corner patch 130.00 pr  
 81Y-850 Cab back patch (no hump), 38-40 120.00 ea  
 11Y-850 Cab back patch with hump, 41-47 125.00 ea